

**BRESSAN ALTO RECORDER**

AREAS OF HORN 1 FOOT ARE VARNISHED WITH A QUITE THICK BLACK VARNISH. CENTRE SHOWS TRACES OF DARK COLOUR PENETRATING THE GRAIN, ESPECIALLY ON THE QUARTERED SECTIONS, AND WHERE THE WOOD IS FLAMED. FROM THUMB-HOLE UP HAS BEEN RESTORED BY HANS COOLSMAN WITH NEW BOXWOOD AND BRASS. CORK AT THE JOINTS. FOOT (CA. 10.6 CM LONG) HAS BEAUTIFUL PROPORTION AND A VERY FINE LINE, WITH THE NARROWER IVORY BANDS.

BOXWOOD WITH IVORY MOUNTS.

NEW BLOCK AND OTHER REPAIRS & RESTORATION BY HANS COOLSMAN, UTRECHT



MEASURED & DRAWN BY F.G. MORGANT AUGUST 6TH. 1979

RECENT HISTORY - USED AS A CHURCH CHOIR PITCH PIPE FOR MANY YEARS. AN ATTEMPT WAS MADE TO RAISE THE PITCH BY SHORTENING THE CENTRE JOINT. REPAIR AND RESTORATION WAS DONE TO RETURN TO THE ORIGINAL PITCH, AS DETAILED.

